

FEB 1 5 2005

400 Seventh Street, SW Washington, DC 20590

Recall Date: January 24, 2005

National Highway Traffic Safety Administration

> NVS-215kjs 05T-001

MR. CURTIS DECKER
NATIONAL MANAGER
CONTINENTAL TIRE NORTH AMERICA, INC.
1800 CONTINENTAL BLVD.
CHARLOTTE, NC 28273

Subject: POSSIBLE TIRE FAILURE

Dear MR. DECKER:

This letter is to acknowledge your recent defect or noncompliance information report. Please review the following information to ensure that it conforms to your records.

Makes/Models/Model Years:

CONTINENTAL/HDL

CONTINENTAL/HSL

CONTINENTAL/HSR

CONTINENTAL/HSR

CONTINENTAL/HTL

GENERAL/S380A

GENERAL/ST250

TOYO/M122

TOYO/M122

TOYO/M127

YOKOHAMA/RY023

YOKOHAMA/RY023

YOKOHAMA/RY587

YOKOHAMA/RY587

YOKOHAMA/RY617

YOKOHAMA/TY517

YOKOHAMA/TY517

NHTSA Campaign Number: 05T-001

Components:

TIRES

Potential Number of Units Affected: 143

1

Summary:

THE RUBBER COMPOUND USED IN THE SHOULDER PAD COMPONENT OF THE TIRE IS NOT CORRECT

Consequence:

THE OVERALL DURABILITY OF THE TIRE IS REDUCED, WHICH IF DRIVEN UNCHECKED, THE TIRE COULD DEGRADE, POSSIBLY RESULTING IN A VEHICLE CRASH.

Remedy:

CONTINENTALTOYO, AND YOKOHAMA WILL NOTIFY ITS CUSTOMERS AND REPLACE THE TIRES FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING FEBRUARY 2005.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Your contact for this recall will be KELLY SCHULER, who may be reached by phone at 202-366-5227 or by email at KSCHULER@NHTSA.DOT.GOV. We look forward to working with you for successful completion of this recall campaign.

George H. Person

Chief, Recall Management Division Office of Defects Investigation

Enforcement

Sincerely,